

SUPER HS PREMIUM CLEAR COAT



Technical Data Sheet:

07.2022



Product Details:

Product Name:	Super HS Premium Clear Coat
Product Description:	<p>Germa-Tech Super High Solid Premium Clear Coat is a high performance double component clear coat, super high gloss, good build, strong chemical resistant, excellent color and gloss protective power, suitable for overall spraying and refinish</p> <p>Requires full 60min bake.</p>

Substrates:

	1K Basecoat
-------------------------------------------------------------------------------------	-------------

Surface Preparation:

	Clean the surface with a Germa-Tech Tack Cloth to remove dust and particles from the surface.
-------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------



Directions For Use:
Mixing Ratio:


	Clear Coat +	Hardener +	Thinner
	2	1	0-10%
< 18 °C	Premium Clear Coat	Premium Fast Hardener	Standard Reducer
18 - 24 °C	Premium Clear Coat	Premium Standard Hardener	Standard Reducer
25 - 30 °C	Premium Clear Coat	Premium Standard Hardener	Standard Reducer
> 30 °C	Premium Clear Coat	Premium Slow Hardener	Standard Reducer

Pot Life:

Pot-Life at 25 °C

3-4 Hours

Shelf Life:

Shelf Life is up to 36 months if unopened and stored in a cool dry place (below 20°C). Shelf life is an optimal guide and the product is manufactured and tested to exceed shelf life recommendations, avoid ambient temperatures above 20 and exposure to direct sunlight which are amongst common factors that will diminish storage shelf life. Contact the distributor or manufacturer if requiring further advice.

If stored correctly, it can be used for up to 12 months from opening the original seal

Spray Gun Set Up:


Gravity Feed: 1.2-1.5mm Suction Feed: 1.4-1.7mm

Conventional: 3-4 bar RP: 2.0-2.5 bar HVLP: 2.0 bar

Coats And Thickness:


Coats & Thickness	2-3 Coats, total 50-70um
------------------------------	--------------------------

Spray viscosity (20°C, Ford Cup DIN 4) 16-18 seconds

At 20 °C, 5-10 minutes between coats, 15-20 minutes before baking

WARNING

A flash of is required between each coat, flash off time should be adjusted +/- depending on air temperature. Fast and Slow hardeners and reducers can be used in extreme cold or extreme heat.

A flash time of 15-20 min is required before commencing of the bake.

Drying Time: 	<table border="1"> <thead> <tr> <th>Temperature:</th> <th>Dust Free</th> <th>Dry to Polish (FULL BAKE)</th> </tr> </thead> <tbody> <tr> <td>Below 15 °C</td> <td colspan="2">Recommend Full Bake</td> </tr> <tr> <td>23 °C</td> <td>10 Hours</td> <td>16 - 24 hours</td> </tr> <tr> <td>60 °C</td> <td>30 minutes</td> <td>60 minutes</td> </tr> </tbody> </table>			Temperature:	Dust Free	Dry to Polish (FULL BAKE)	Below 15 °C	Recommend Full Bake		23 °C	10 Hours	16 - 24 hours	60 °C	30 minutes	60 minutes
	Temperature:	Dust Free	Dry to Polish (FULL BAKE)												
	Below 15 °C	Recommend Full Bake													
	23 °C	10 Hours	16 - 24 hours												
60 °C	30 minutes	60 minutes													
DRY TO POLISH															
<p>Polishing and denibbing of clear coats requires sufficient dry time. Ensure bake times commence from when the oven reaches temperature of 60 °C and not before. Dry times are greatly impacted by the thickness of the coating and the ambient air temperature when applying. <u>When temperatures are below 23 °C adjust drying times or increase baking times accordingly.</u></p>															
WARNING															
Do not dry in direct sunlight and allow 24 hours or full bake, temperatures in directly sunlight can exceed 70 °C															

Additional Information

Notes:

1. At temperatures lower than 15°C, air-dry at ambient temperature is not recommended. Allow a full bake at 60°C.
2. Mix the clear coat according to the proportion indicated by the manufacturer. The mixture should be used within 2 hours. Only use Germatech reducer.
3. At low humidity, flash off time 2-3 minutes is recommended to achieve smooth paint film.
4. At an ambient temperature higher than 30°C, add Retarder Solvent or Slow Reducer maybe required to avoid blushing. For details please refer to the Retarder Solvent TDS.
5. In the overspray area of new and existing finish, apply directly Thinner SRA to achieve an invisible transition.
6. In the event of fisheyes during application, add 0.5-1% Anti Silicon in the remaining paint and respray the affected area.

WARNING

7. Maximum coating thickness after application of clear coat, cannot exceed 300um (micron), application of product in excess of 300um can result in adverse outcomes and may require sanding back of product, refer Germatech Coating Thickness Guide.
8. Germatech Polyurethane product takes up to 12 weeks to fully cure, if reworking or sanding clear imperfections, utmost care must be taken not to break through the clear layer into the exposed basecoat, reapplication of product directly on sublayers

can results in product reactions. Sand imperfections with P1500 working to P3000 then polish.

9. Germatech Polyurethane products are specifically designed to work with the Germatech product suite ie fillers, primers, basecoat, hardeners and reducer

Packaging: 1U4L

The information contained in this file is presented in good faith based on thorough laboratory and field testing but without warranty. As we have no control over the conditions under which these products are used, it is recommended that all products be tested by the end user to ensure the suitability of the product for the particular application and conditions.